	FORM 1 8-68	120 USE P	REVION	EUS S			~ 1		. 242 4 670	~ .	. A C'AC			MFG, 6-63					
			Δ		l Can Dalas	- 4 0 6 0 7						AGE	~~~~	00000	40000 4		UTING		
	DATE				l For Rele	ı							9KD	2	10066-4		10	4 plut gr p 	
		0717Z	15	NOV	63	T	O F	S	E	C	RE	T		3	 		11		
عوز						-		********	خالم آن					4			12		
:			# =#4				CALLES			7	un en en			5	······································		13	·	
•	το	+ DIR	ECTO	R										7			14	<u> </u>	
25X1A	FROM													8			16		
23 A I A	r rwa	·										•							
	ACTIC	OSA	1-2	0				,							FL	ASH			
	INFO							((=
	## O	•														1			
																	I N5	Ø558	
		TOR:	070	97 1	5 NOV 6	7			•		•								
:					-			=44.5								_الـ			==
25X1A	TO	FLASH				INFO									CITE			0545	
25X1A 🛼					-					-						_		25X1A	١
		*(*************************************																25X1A	
25X1A -		RE:	A.		569														
		1	В.		0544														
•		•	9									,							
25X1A		1.			AB0	RTED	MSN	324	10	AP	PRO	X 180	a nm	NORT	H OF [25X1A	
25X1		AT				DN AD	^ 11415		~^!	D B	en.	CAD (@/\11	ተህ ለፍ	THE I	นกอา			
		u1				TH W	O 0:45	, 01		ĸΚ	EU	rmn i	マレリ	IU OL	ARE I	nu D I	1166		
		ARE A.																	
		2.	RF	F B	WAS SUB	MITTE	D PR	101	R T	0	REC	EIPT	OF	REF	A. W1	e Br	ELIEV	Æ	

2. REF B WAS SUBMITTED PRIOR TO RECEIPT OF REF A. WE BELIEVE THAT A FUEL CONTROL CHANGE WILL CORRECT THE PROBLEM AND WILL TEST HOP AFTER INSTALLATION IS COMPLETE TO CHECK OPERATION AT ALTITUDE WITH NEW FUEL CONTROL. WILL KEEP YOU INFORMED.

END OF MESSAGE